

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2021

Submitted Date:

04/14/2021

Document Number:

689805593**FIELD INSPECTION FORM**Loc ID 439603 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------------|--------------|--|---------------------------------|
| Inspections, General | | sandridgeenvironmental@sandridgeenergy.com | All Inspections |
| Boyer, David | 303-994-0000 | david@d90energy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 444609 | WELL | PR | 12/01/2018 | OW | 057-06539 | Gregory 0780 1-9H | PR |
| 448055 | WELL | PR | 12/15/2017 | OW | 057-06586 | Castle 0780 6-17H20 | PR |
| 448056 | WELL | PR | 12/15/2017 | OW | 057-06587 | Castle 0780 5-17H20 | PR |
| 448057 | WELL | PR | 08/10/2018 | OW | 057-06588 | Castle 0780 8-17H20 | PR |
| 448058 | WELL | PR | 07/31/2018 | OW | 057-06589 | Castle 0780 7-17H20 | PR |
| 452319 | WELL | PR | 09/01/2018 | OW | 057-06603 | Janet 0780 1-16H21 | PR |
| 452320 | WELL | PR | 09/01/2018 | OW | 057-06604 | Janet 0780 2-16H21 | PR |
| 452321 | WELL | PR | 09/01/2018 | OW | 057-06605 | Janet 0780 4-16H21 | PR |
| 452339 | WELL | PR | 09/01/2018 | OW | 057-06606 | Janet 0780 3-16H21 | PR |

General Comment:

[Routine FIU inspection.](#)

[Signs on location not updated to reflect current operator.](#)

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Tank battery sign incomplete. Tank Battery sign must include: operator name, telephone number where operator can be reached at all times, telephone number for local emergency services (911 where available), the public road used to access the site, well name, API numbers, and legal location for all wells associated with battery, location of battery including the quarter/quarter section. | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | Date: | 05/12/2021 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. Tank labels should contain: name of operator, operator emergency contact number, tank capacity, tank contents, NFPA label. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 05/12/2021 |
| Type | WELLHEAD | | |
| Comment: | Sign not posted or information inaccurate at well(s). Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 05/12/2021 |

Emergency Contact Number:

Comment: Sign not updated to reflect current operator.

Corrective Action: Install sign to comply with Rule 605.g.

Date: 05/12/2021

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|-----------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # | | |
| Comment: | No bradenhead access apparent. | | |
| Corrective Action: | Install bradenhead access and/or means of monitoring bradenhead pressure OR confirm bradenhead monitoring/access via telemetry or other means via FIRR. | Date: | 05/12/2021 |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|-------------------------------|-----------|-------|
| Type: Other | # 3 | |
| Comment: | Jet pumps | |
| Corrective Action: | | Date: |
| Type: Horizontal Separator | # 6 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Pump Jack | # 7 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Emission Control Device | # 8 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 1 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 444609 | Type: | WELL | API Number: | 057-06539 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 448055 | Type: | WELL | API Number: | 057-06586 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 448056 | Type: | WELL | API Number: | 057-06587 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 448057 | Type: | WELL | API Number: | 057-06588 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 448058 | Type: | WELL | API Number: | 057-06589 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452319 | Type: | WELL | API Number: | 057-06603 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452320 | Type: | WELL | API Number: | 057-06604 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452321 | Type: | WELL | API Number: | 057-06605 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452339 | Type: | WELL | API Number: | 057-06606 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Producing Well

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Culverts | | | | |
| Rip Rap | | | | | | |
| Sediment Traps | | | | | | |
| Gravel | | | | | | |
| | | Compaction | | | | |
| Berms | | | | | | |
| | | Rip Rap | | | | |
| Compaction | | | | | | |
| | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 689805609 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5402790 |