

Inspection Photos
Location Name: Gensis #3, 9-2
Location ID: 319579



Photo 1: Pumpjack Sign



Photo 2: Storage of supplies

Inspection Photos
Location Name: Gensis #3, 9-2
Location ID: 319579



Photo 3: Stained soil, trash



Photo 4: Disconnected equipment



Inspection Photos
Location Name: Gensis #3, 9-2
Location ID: 319579



Photo 5: Equipment disconnected, stained soil, trash



Photo 6: disconnected equipment

Inspection Photos
Location Name: Gensis #3, 9-2
Location ID: 319579




Photo 7: Stained soil, no sign



Photo 8: Tank not grounded

Inspection Photos
Location Name: Gensis #3, 9-2
Location ID: 319579



Photo 9: Stained soil, trash