

Inspection Photos
Location Name: Nielson #4
API: 05-007-06117



Nielson #4 well head, pump jack, and location sign. Location sign does not meet the requirements of Rule 605.d(1).



Well head is wet and surrounding soil is stained.

Inspection Photos
Location Name: Nielson #4
API: 05-007-06117



300 bbl. steel AST for Nielson #4. Stained soil at load out valve. Battery sign is non-compliant.



Anchor observed during this inspection. Tank is not anchored.