

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891




Photo 1 – Location Sign at Entrance

Photo 2 – Wellhead

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 3 – Heater Treater

Photo 4 – Tank Battery

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 5 – ECD and Flare

Photo 6 – Exhaust – Stained Soil

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 7 – Gas Engine – Stained Soil

Photo 8 – Gas Engine