

Inspection Photos
Location Name: Antelope 14-20
Location ID: 423766



Photo #1 Wells & Weeds



Photo #2 Production Equipment

Inspection Photos
Location Name: Antelope 14-20
Location ID: 423766



Photo #3 Tank Battery



Photo #4 Sign not legible



Inspection Photos
Location Name: Antelope 14-20
Location ID: 423766



Photo #5 Sign not legible



Photo #6 Trash



Inspection Photos
Location Name: Antelope 14-20
Location ID: 423766



Photo #7 Trash



Photo #8 Stained Soil

Inspection Photos
Location Name: Antelope 14-20
Location ID: 423766



Photo #9 Stained Soil



Photo #10 Stained Soil



Inspection Photos
Location Name: Antelope 14-20
Location ID: 423766




Photo #11 Weathered NFPA Placard



Photo #12 Cement Debris



Inspection Photos
Location Name: Antelope 14-20
Location ID: 423766



Photo #13 Trash



Photo #14 Trash

Inspection Photos
Location Name: Antelope 14-20
Location ID: 423766



Photo #15 Unused Equipment

