

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #1 Location



Photo #2 Riser is unmarked & not locked out

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004




Photo #3 Unused Equipment




Photo #4 Stained soil and unmarked/ not locked out risers



Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #5 Stained soil & Waste




Photo #6 Stained soil

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004




Photo #7 Missing Labels



Photo #8 Missing Labels

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #9 Stained soil



Photo #10 Stained soil

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004




Photo #11 Mechanical Conditions



Photo #12 Unused Equipment

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004




Photo #13 Stained soil



Photo #14 Stained soil

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #15 Weeds



Photo #16 Weeds

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #17 Trash



Photo #18 Weeds

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004




Photo #19 Weathered Placard



Photo #20 Weathered Placards



Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #21 Weather content label



Photo #22 Trash



Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #23 Stained soil




Photo #24 Stained soil & Unused Equipment



Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #25 Mechanical Conditions




Photo #26 Mechanical Conditions

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #27 Unused Equipment




Photo #28 Stained Soil/ Unused Equipment

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004




Photo #29 Stained soil




Photo #30 Stained soil

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004




Photo #31 Unused Equipment



Photo #32 Unused Equipment

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004




Photo #33 Stained Soil



Photo #34 Mechanical Conditions

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004




Photo #35 Stained Soil




Photo #36 Unused Equipment

Inspection Photos
Location Name: State Antelope P-30 Pad
Location ID: 433004



Photo #37 Mechanical Conditions