

Inspection Photos

4/12/2021

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335929

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335929



Photo 1: Photo shows sign at Location entrance.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335929



Photo 2: Photo taken from the northwest corner of the Location, facing north. Photos 2-3 provide an overview of the Production area from north, east, to south.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335929



Photo 3: See comments under photo 2.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335929



Photo 4: See comments under photo 2.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335929



Photo 5: Photo taken from the southern interim areas of the Location, facing south. Photo shows areas where topsoil does not appear to have been replaced during interim reclamation of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335929



Photo 6: Photo taken from the southern interim areas of the Location, facing southeast. Photo shows areas where topsoil does not appear to have been replaced during interim reclamation of the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 335929



Photo 7: Photo taken from the northeastern end of the Location, facing north. Photo shows interim areas where topsoil appears to have been replaced, and is progressing towards COGCC 1003 revegetation standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335929



Photo 8: 2019 COGIS aerial imagery. Photo shows areas on the south end of the Location where topsoil does not appear to have been replaced in accordance with 1003.e.(2).