



**Inspection Photos**  
**Location Name: Nessu 2**  
**Location ID: 336277**



**Photo 1 WH sign**

**Photo 2 Stained soil around WH.**

**Inspection Photos**  
**Location Name: Nessu 2**  
**Location ID: 336277**



**Photo 3 Valves on WH are closed**

**Photo 4 Valve on WH are closed .**

**Inspection Photos**  
**Location Name: Nessu 2**  
**Location ID: 336277**



**Photo 5 braden head gauge not in working order missing cover.**

**Photo 6 Pump Jack.**

**Inspection Photos**  
**Location Name: Nessu 2**  
**Location ID: 336277**



**Photo 7 WH gauge numbers not visible through cover.**

**Photo 8 Rod does not appear to have moved for awhile.**

**Inspection Photos**  
**Location Name: Nessu 2**  
**Location ID: 336277**



**Photo 9 transformers.**

**Photo 10 electric panel.**

**Inspection Photos**  
**Location Name: Nessu 2**  
**Location ID: 336277**



**Photo 13 Meter box .**

**Photo 14 Unused Wiring in conduit next to electric panel.**

Inspection Photos  
Location Name: Nessu 2  
Location ID: 336277



Photo 11 Electric panel is shut off .

Photo 9 Electric panel switch to PJ motor is Shut off.