

Inspection Photos
Location Name: Nessu 15
Location ID: 317831



Photo 1 WH sign

Photo 2 Dead weeds around WH.

Inspection Photos
Location Name: Nesssu 15
Location ID: 317831



Photo 3 Valves on WH are closed, broken gauge.

Photo 4 Valves on WH are closed.

Inspection Photos
Location Name: Nessu 15
Location ID: 317831



Photo 5 Valves on WH are closed dead weeds.

Photo 6 valves closed and tagged out dead weeds.

Inspection Photos
Location Name: Nesssu 15
Location ID: 317831



Photo 7 gauge glass is hazed over numbers not visible.

Photo 8 Dead weeds around Pump Jack base and WH.

Inspection Photos
Location Name: Nesssu 15
Location ID: 317831



Photo 9 electric panel and meter box.

Photo 10 meter box

Inspection Photos
Location Name: Nesssu 15
Location ID: 317831



Photo 11 Electric panel.

Photo 12 electric panel is shut off and tagged out.