

Inspection Photos
Location Name: Nesssu 13
Location ID: 317947



Photo 1 WH sign

Photo 2 WH.

Inspection Photos
Location Name: Nesssu 13
Location ID: 317947



Photo 3 pump jack



Photo 4 Valves shut on WH.

Inspection Photos
Location Name: Nessu 13
Location ID: 317947



Photo 5 braden head gauge missing cover

Photo 6 WH gauge well is tagged out.

Inspection Photos
Location Name: Nesssu 13
Location ID: 317947



Photo 7 unused wiring inside conduit pipe

Photo 8 Meter box.

Inspection Photos
Location Name: Nesssu 13
Location ID: 317947



Photo 9 Electric panel in off position and tagged out