

Inspection Photos
Location Name: Nesssu 14
Location ID: 318302



Photo 1 WH sign

Photo 2 WH.

Inspection Photos
Location Name: Nesssu 14
Location ID: 318302



Photo 3 pump jack



Photo 4 Valves shut on WH.

Inspection Photos
Location Name: Nessu 14
Location ID: 318302



Photo 5 braden head gauge missing cover and needle is missing.

Photo 6 Dead weeds along West side of pump jack/WH.

Inspection Photos
Location Name: Nessu 14
Location ID: 318302



Photo 7 Dead weeds next to electric panel/meter box

Photo 8 Meter box.

Inspection Photos
Location Name: Nessu 14
Location ID: 318302



Photo 9 Dead weeds next to electric panel/meter box

Photo 10 electric panel shut off and tagged out.

Inspection Photos
Location Name: Nessu 14
Location ID: 318302



Photo 11 Dead weeds next to electric panel/meter box