

Inspection Photos
Location Name: Harriet W. Lucke #1
Location ID: 317795



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Harriet W. Lucke #1
Location ID: 317795



Photo 3 Valve closed and tagged out