

Inspection Photos
Location Name: KPK Nessu 14
Location ID: 05-123-07724



Well head valves closed Tagged out



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources