

Inspection Photos

Location Name: VALCAR-USX A-66N64W /3SESW

Location #: 306406



Colorado Oil & Gas Conservation Commission
Weld
+40.509309, -104.539191
70° E
13-Apr-2021 15:30

Photo #1

Valcar-USX A 3-14 (05-123-24596) Wellsite

Producing | PR



Colorado Oil & Gas Conservation Commission
Weld
+40.510412, -104.545339
144° SE
13-Apr-2021 15:54

Photo #2

Rodriguez 3-3-19, 3-35, Egge 3-32, Valcar-USX A 3-14

Battery site

Active

Formerly served:

Dinges 3-33

Plugged & Abandoned | PA



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: VALCAR-USX A-66N64W /3SESW

Location #: 306406



Colorado Oil & Gas Conservation Commission
Weld
+40.510308, -104.545339
68° E
13-Apr-2021 15:54

Photo #3

Rodriguez 3-3-19, 3-35, Egge 3-32, Valcar-USX A 3-14

Battery site

Active

Battery sign



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources