

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/14/2021

Submitted Date:

04/14/2021

Document Number:

700702588

FIELD INSPECTION FORM

Loc ID 334690	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635				Findings: 15 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211024	WELL	PR	12/01/2020	GW	045-06782	QUARTER CIRCLE 43-33H	PR
290944	WELL	PR	06/06/2007	GW	045-14235	WILLIAMS RWF 442-33	PR
290945	WELL	PR	06/06/2007	GW	045-14234	WILLIAMS RWF 433-33	PR
290946	WELL	PR	06/06/2007	GW	045-14233	WILLIAMS RWF 533-33	PR
290947	WELL	PR	01/11/2008	GW	045-14232	WILLIAMS RWF 333-33	PR
298902	WELL	PR	08/31/2010	GW	045-17465	WILLIAMS RWF 413-34	PR
298903	WELL	PR	06/06/2010	GW	045-17466	WILLIAMS RWF 44-33	PR
298904	WELL	PR	05/30/2014	GW	045-17467	WILLIAMS RMV 131-34	PR
298906	WELL	PR	01/01/2012	GW	045-17469	WILLIAMS RWF 313-34	PR

General Comment: <p>COGCC Inspection Report Summary</p> <p>On Wednesday 4/14/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Quarter Circle 43-33H, at Location # 334690 in Garfield county Colorado.</p> <p>While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.</p> <p>During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Location show signs of lack of stabilization/compaction and evidence of sediment moving from location (tracking) 2. Tank labels are illegible (quantity) <p>Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>
--

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Some Tank labels are illegible (quantity)		
Corrective Action:	Install proper labeling	Date:	05/14/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 4		
Comment:	Three (3) chemical tanks are at well heads in plastil containments and One (1) 500 gallon methanol tank is at separators in a metal containment		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 9		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	200 BBLs	HEATED STEEL AST		,	
Comment:	fresh water for fire suppression					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	11	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211024	Type:	WELL	API Number:	045-06782	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	290944	Type:	WELL	API Number:	045-14235	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	290945	Type:	WELL	API Number:	045-14234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	290946	Type:	WELL	API Number:	045-14233	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	290947	Type:	WELL	API Number:	045-14232	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	298902	Type:	WELL	API Number:	045-17465	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	298903	Type:	WELL	API Number:	045-17466	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	298904	Type:	WELL	API Number:	045-17467	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			
Ditches						
Compaction	Fail					
Berms						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.
1. Location show signs of lack of stabilization/compaction and evidence of sediment moving from location (tracking)

Corrective Action: **Install or repair required BMPs**

Date: 05/14/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702592	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403900