

Final Reclamation and Stormwater Inspection

April 13, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 331561

Inspection Document #: 697502765

Weld County, CO

NESW Section 5 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources_S

Inspection Photos

Location Name: WYSCAVER 23-5

Location ID: 331561



Photo 1. Drone aerial imagery from 4/13/2021 illustrates the associated offsite tank battery which was a shared tank battery. PDC's shared portion is highlighted in the red-dashed line. Wind erosion was observed on PDC's shared portion of the tank battery which is transporting sediment offsite, some of which is going onto Noble's shared portion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502765




Photo 2. Photo taken from PDC's shared portion of the tank battery, facing South. Photo illustrates eolian (wind) deposition which is accumulating along Noble's northern tank battery. Some of this deposition could also be from nearby reference areas to the north. Regardless, PDC's shared portion of the tank battery is not stabilized to minimize erosion, transport of sediment offsite, and site degradation.

Inspection Photos
Location Name: WYSCAVER 23-5
Location ID: 331561



Photo 3. Photo taken from PDC's shared portion of the tank battery, facing North. See comments under Photo 2.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502765



Photo 4. Drone aerial imagery from 4/13/2021, facing Southeast. Photo illustrates the well location access road which has not been properly reclaimed.

Inspection Photos
Location Name: WYSCAVER 23-5
Location ID: 331561



Photo 5. Photo taken from a portion along the well location access road, facing Southeast. Photo illustrates the access road has not been properly reclaimed.



Photo 6. Photo taken from a portion along the well location access road, facing Northwest. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502765

Inspection Photos
Location Name: WYSCAVER 23-5
Location ID: 331561



Photo 7. Photo taken from the well location, facing West. Photo illustrates little to no establishment of desirable plant species.

