

# Final Reclamation and Stormwater Inspection

April 13, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 331801

Inspection Document #: 697502767

Weld County, CO

NWSW Section 5 T4N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources<sub>S</sub>

Inspection Photos  
Location Name: WYSCAVER #13-5  
Location ID: 331801



**Photo 1.** Drone aerial imagery from 4/13/2021, facing North. Photo illustrates the well location access road which has not been properly reclaimed.



Inspection Photos  
Location Name: WYSCAVER #13-5  
Location ID: 331801



**Photo 2.** Photo taken from a portion along the well location access road, facing Southeast. Photo illustrates the access road has not been properly reclaimed.



**Photo 3.** Photo taken from a portion along the well location access road, facing Northwest. See comments under Photo 2.

Inspection Photos  
Location Name: WYSCAVER #13-5  
Location ID: 331801



**Photo 4.** Photo taken from the well location, facing South. Photo illustrates little to no establishment of desirable plant species.



Inspection Photos  
Location Name: WYSCAVER #13-5  
Location ID: 331801



**Photo 5.** Photo taken from the well location, facing Southwest. See comments under Photo 4.



Inspection Photos  
Location Name: WYSCAVER #13-5  
Location ID: 331801



**Photo 6.** Photo taken from the well location, facing West. See comments under Photo 4.



Inspection Photos  
Location Name: WYSCAVER #13-5  
Location ID: 331801



**Photo 7.** Photo taken from the well location, facing North. See comments under Photo 4.

