

# Inspection Photos

API: 071-07197

Operator: OGRIS OPERATING LLC

Inspection Date: 4/14/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07197 | Date: 4/14/2021

Inspection Photos



**Photo 1.** Facing north at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07197 | Date: 4/14/2021

Inspection Photos



**Photo 2.** Facing west at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07197 | Date: 4/14/2021

## Inspection Photos



**Photo 3.** Facing south toward the interim reclamation area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07197 | Date: 4/14/2021