

Final Reclamation Inspection

April 13, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 305924

Inspection Document #: 697502775

Weld County, CO

SENW Section 5 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Foley #22-05
Location ID: 305924



Photo 1. Photo taken from the well location, facing South. Photo illustrates Operator has removed all equipment from location but has not completed all of the required reclamation activities.



Inspection Photos
Location Name: Foley #22-05
Location ID: 305924



Photo 2. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: Foley #22-05
Location ID: 305924



Photo 3. Photo taken from the well location, facing North. See comments under Photo 1.



Inspection Photos
Location Name: Foley #22-05
Location ID: 305924



Photo 4. Photo taken from the well location, facing North. Photo illustrates the access road that needs to be reclaimed.

Also, the associated offsite tank battery is observed in the background, which is still active and in use for other nearby wells.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502775