

Inspection Photos
Location Name: Sebold Dorothy B #2
Location ID: 318909



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Sebold Dorothy B #2
Location ID: 318909



Photo 3 WH valves closed




Photo 4 WH electric panel shut off and tagged out