

Inspection Photos
Location Name: Wattenberg Henry E unit B2
Location ID: 332979



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Wattenberg Henry E unit B2
Location ID: 332979



Photo 3 WH valves closed and tagged out