

Inspection Photos
Location Name: Doversberger Eugene #3
Location ID: 318410



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Doversberger Eugene #3
Location ID: 318410



Photo 3 WH valves are shut

Photo 4 WH electric panel is shut off and tagged out