

Inspection Photos  
Location Name: Doversberger Eugene #2  
Location ID: 317757




Photo 1 WH sign

Photo 2 WH

Inspection Photos  
Location Name: Doversberger Eugene #2  
Location ID: 317757



Photo 3 WH valves are shut

Photo 4 WH electric panel is shut off and tagged out