

Inspection Photos
Location Name: Suckla Brown unit 17
Location ID: 318596



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Suckla Brown unit #17
Location ID: 318596



Photo 3 WH valves are shut

Photo 4 WH Electric panel is shut off and tagged out