




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Ant Hill Unit 8-12

API: 05-103-10993

Inspection: 701500332



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.


Ant Hill Unit 8-12

API: 05-103-10993

Inspection: 701500332



40.16105, -108.18993, 6485.8ft, 56°
04/14/2021 03:33:18 PM





40.16105, -108.18985, 6457.8ft, 89°
04/14/2021 03:35:43 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tanks.

Ant Hill Unit 8-12

API: 05-103-10993

Inspection: 701500332



40.16106, -108.18997, 6490.0ft, 80°
04/14/2021 03:32:46 PM



40.16097, -108.18993, 6470.1ft, 325°
04/14/2021 03:32:20 PM



40.16139, -108.18968, 6466.9ft, 241°
04/14/2021 03:34:56 PM

