

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402589958
Receive Date:
04/15/2021
Report taken by:
ROB YOUNG

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>FOUNDATION ENERGY MANAGEMENT LLC</u>	Operator No: <u>10112</u>	Phone Numbers
Address: <u>5057 KELLER SPRINGS RD STE 650</u>		
City: <u>ADDISON</u>	State: <u>TX</u>	Zip: <u>75001</u>
Contact Person: <u>Alyssa Beard</u>	Email: <u>abeard@foundationenergy.com</u>	
		Phone: <u>(303) 244-8114</u>
		Mobile: <u>()</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION
Remediation Project #: 17700 Initial Form 27 Document #: 402589958

PURPOSE INFORMATION

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other _____

SITE INFORMATION N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>477237</u>	API #: _____	County Name: <u>YUMA</u>
Facility Name: <u>Water Gathering Line</u>	Latitude: <u>40.079387</u>	Longitude: <u>-102.563878</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NESW</u>	Sec: <u>6</u>	Twp: <u>1N</u>	Range: <u>46W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Crop land

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Water well within 1/4 mile is for livestock

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	3120 sq ft	Visual observation & soil sampling

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Two soil samples were collected from the spill path and sent to American Agricultural Lab in McCook, NE in order to determine the necessary volume of soil amendments. Two soil samples were collected from along the spill path and showed levels of SAR and soluble salts exceeding the COGCC standard for inorganics (analytical results were reported on Supplement Form 19). Results were used to calculate the amount of agricultural gypsum to be applied.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Six (6) samples will be collected by hand auger every 40' along the spill path and analyzed for COGCC Table 915-1 inorganics. Analytical results will be reported on a Supplemental Form 27.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

TBD.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 10
Number of soil samples exceeding 910-1 10
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 3120

NA / ND

NA Highest concentration of TPH (mg/kg) _____
-- Highest concentration of SAR 130
BTEX > 910-1 No
Vertical Extent > 910-1 (in feet) 4

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet) 25
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 910-1 _____

_____ Highest concentration of Benzene (µg/l) _____
_____ Highest concentration of Toluene (µg/l) _____
_____ Highest concentration of Ethylbenzene (µg/l) _____
_____ Highest concentration of Xylene (µg/l) _____
_____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
_____ Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

* Updated, 4/15/21 - On March 9, 2021, Foundation collected six soil samples from within the original spill path using a hand auger advanced to 12" and 36" at each location. The samples were run for the reclamation constituents of Table 915. Foundation proposes to collect soil samples semi-annually, if not more frequently, and submit the results on a Form 27 to track the progress of remediation. Also to be included in future Form 27's will be the dates and quantities of gypsum application. This location had ~100 lbs of granular gypsum spread on it in July, 2020 shortly after the spill occurred. SAR concentrations ranging from 65 in the West@36" sample, to 130 in the East @12" sample, indicate that additional gypsum needs to be applied quarterly and soil monitoring through sampling will continue until concentrations of SAR and Boron are within the Table 915 standard.

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The source has been and is planned to be treated in-situ with agricultural gypsum.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Agricultural gypsum has been applied to the affected area based on analytical results of soil samples collected in July 2020.

Soil Remediation Summary

In Situ

Ex Situ

Yes Bioremediation (or enhanced bioremediation)

 Excavate and offsite disposal

No Chemical oxidation

 If Yes: Estimated Volume (Cubic Yards)

No Air sparge / Soil vapor extraction

 Name of Licensed Disposal Facility or COGCC Facility ID #

No Natural Attenuation

 Excavate and onsite remediation

No Other

 Land Treatment

 Bioremediation (or enhanced bioremediation)

 Chemical oxidation

 Other

Groundwater Remediation Summary

 Bioremediation (or enhanced bioremediation)

 Chemical oxidation

 Air sparge / Soil vapor extraction

 Natural Attenuation

 Other

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: Quarterly Semi-Annually Annually Other _____

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The location was treated with agricultural gypsum, then turned, disced, and seeded in January 2021. Some growth has been seen in spring 2021. Gypsum applications will continue quarterly and vegetation monitored.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim? Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 07/14/2020

Actual Spill or Release date, if known. 07/14/2020

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). _____

Date of commencement of Site Investigation. 07/15/2020

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. 07/29/2020

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

This Form 27 is being filed as an update for this remediation project with the results of recent soil samples included. Thanks

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Alyssa Beard _____

Title: EHSR Manager _____

Submit Date: 04/15/2021 _____

Email: regulatory@foundationenergy.com _____

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: ROB YOUNG _____

Date: 04/16/2021 _____

Remediation Project Number: 17700 _____

Condition of Approval**COA Type****Description**

	Provide a photolog, soil sample analytical data table and laboratory reports, soil amendment application logs and proposed plans for the next quarter's site activities on the next quarterly Form 27 submittal.
1 COA	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402589958	FORM 27-INITIAL-SUBMITTED
402644614	ANALYTICAL RESULTS
402644620	ANALYTICAL RESULTS
402659960	SOIL SAMPLE LOCATION MAP

Total Attach: 4 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)