



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Ant Hill Unit 18-44**

**API: 05-103-10209**

**Inspection: 701500346**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Storm water channel at meter building  
& separator.**

**Ant Hill Unit 18-44**

**API: 05-103-10209**

**Inspection: 701500346**









40.13684, -108.19994, 6131.0ft, 98°  
04/14/2021 05:13:35 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Pig station.**

**Ant Hill Unit 18-44**

**API: 05-103-10209**

**Inspection: 701500346**





40.13643, -108.20001, 6139.1ft, 280°  
04/14/2021 05:08:46 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Tank with hole.**

**Ant Hill Unit 18-44**

**API: 05-103-10209**

**Inspection: 701500346**



40.13647, -108.20009, 6118.7ft, 300°  
04/14/2021 05:09:04 PM





40.13652, -108.20008, 6140.4ft, 164°  
04/14/2021 05:10:28 PM



40.13652, -108.20009, 6139.7ft, 136°  
04/14/2021 05:09:44 PM





# COUNTY ROAD 142

Lat: 40.13674 Long: 108.20001

31 OPERATING

ANT HILL UNIT #18-44  
SE SE SEC. 18-T2N-R96W  
RIO BLANCO COUNTY, CO  
#C-0127535

IN CASE OF EMERGENCY CALL  
EMERGENCY NUMBER : 800-209-9762

40.13646, -108.19986, 6148.6ft, 71°  
04/14/2021 05:06:46 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 9. Sign on meter building.

Ant Hill Unit 18-44

API: 05-103-10209

Inspection: 701500346