



40.15038, -108.20452, 6298.1ft, 67°
04/14/2021 05:34:06 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 701500350



40.15037, -108.20437, 6299.7ft, 347°
04/14/2021 05:33:45 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 701500350



40.15045, -108.20427, 6312.3ft, 0°
04/14/2021 05:32:56 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 701500350



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 701500350



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Storage building.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 701500350



40.15052, -108.20397, 6313.9ft, 69°
04/14/2021 05:32:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tanks.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 701500350






Photo 8. Container label.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 701500350



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



40 15028, -108.204, 6304 7ft, 123°
04/14/2021 05:30:37 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. Debris.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 701500350

