

Inspection Photos

Loc#479723

Operator: Terra

Insp#: 692403264

Insp Date: 4/5/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

April 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Juhan Tank Facility Loc#479723



Photo#2:

Overview of Location from NE corner. Equipment cellar indicated with arrow.

April 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Juhan Tank Facility Loc#479723



Photo#3:
Equipment cellar referenced in Inspection. Note Debris weeds blown into equipment.



Photo#4:
Escape board referenced in Inspection. Note Debris weeds blown into equipment.

April 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Juhan Tank Facility Loc#479723



Photo#5:
Weeds that have become Debris.



Photo#6:
Senesced weeds that will become Debris.

April 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Juhan Tank Facility Loc#479723