

Inspection Photos
Location Name: F S Duncan B 5
Location ID: 313063



Photo 1. Overview of location taken facing south.



Inspection Photos
Location Name: F S Duncan B 5
Location ID: 313063



Photo 2. No bradenhead access apparent. Dried annual weeds on location.



Photo 3. Incomplete/faded tank label.