

Inspection Photos
Location Name: Duncan "B" 6
Location ID: 312829



Photo 1. Overview of location taken facing south. Dried annual weeds on location.



Inspection Photos
Location Name: Duncan "B" 6
Location ID: 312829



Photo 2. No bradenhead access apparent. Dried annual weeds on location.



Photo 3. Incomplete/faded tank label. Dried annual weeds on location.