

Inspection Photos
Location Name: F S Duncan B 10
Location ID: 313065



Photo 1. Overview of location taken facing north. Dried annual weeds on location.



Inspection Photos
Location Name: F S Duncan B 10
Location ID: 313065



Photo 2. No bradenhead access apparent. Dried annual weeds on location.



Photo 3. Dried annual weeds on location.

