

Inspection Photos
Location Name: Duncan B 11
Location ID: 313127



Photo 1. Overview of location taken facing north. Dried annual weeds on location.



Inspection Photos
Location Name: Duncan B 11
Location ID: 313127



Photo 2. Tank labels faded or incomplete. Dried annual weeds.



Photo 3. No bradenhead access apparent. Dried annual weeds on location.