

Inspection Photos

Facility#479766


Operator: Terra

Insp#: 692403307

Insp Date: 4/14/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to South, and Booster Station.

April 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos:Terra Juhan Booster Station Loc#479766



Photo#2:
Debris in Tank area.



Photo#3:
Debris in Tank area



April 5, 2021



Photo#4:
View of Tank area.

April 5, 2021



Photo#5:
View of Tank area