

**Inspection Photos**  
**Operator: Hilcorp**  
**Facility: 430890**  
**Date: 4/15/2021**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Dense kochia debris up to 4 feet tall observed.



Photo 3. View of kochia debris observed around project facilities.



Photo 4. View of the southern project area dense kochia debris observed.