

Inspection Photos
Location Name: Peltier 2
Location ID: 318425



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Peltier 2
Location ID: 318425



Photo 3 WH valves are closed




Photo 4 WH Electric panel shut off and tagged out