

Inspection Photos
Location Name: Suckla Brown unit NAV 7
Location ID: 317653



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Suckla Brown unit NAV 7
Location ID: 317653



Photo 3 WH valves are closed



Photo 4 WH Electric panel shut off and tagged out