

Inspection Photos
Location Name: Suckla Brown 8
Location ID: 317652



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Suckla Brown 8
Location ID: 317652



Photo 3 WH valves are closed



Photo 4 WH Electric panel shut off and tagged out