



39.77473, -108.61218, 6730.5ft, 12°
04/16/2021 03:27:49 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location viewed from entrance.

Continental 6-22

API: 05-103-08540

Inspection: 701500366



39.77491, -108.61166, 6729.8ft, 259°
04/16/2021 03:34:29 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Location.

Continental 6-22

API: 05-103-08540

Inspection: 701500366








Photo 5. Calibration card.

Continental 6-22

API: 05-103-08540

Inspection: 701500366

Meter S/N
202A 231241
C. 0125677B

IMPACT ANALYTICAL
SYSTEMS INC.
365 SOUTH MAIN
BRIGHTON, CO
80601
303-437-4150
www.impactanalytical.com

Station No. 93482
Station Name Continental 6-22
Producer ~~Rein~~ Arrow Windsor
Sec 22 Township 3S Range 20W
Diff 0-100" Temp Range 0-150°
Static 0-500# Absolute 11.4 PSIA
Type 2.067

| Date | Orifice Plate Size | Meter Test Date | Sample Date |
|---------|-----------------------|--------------------|----------------|
| 5-19-5 | 0.875 | 5-19-5 | 5-9-5 |
| 6-14-6 | 0.875 | 6-14-6 | 6-14-6 |
| 10-9-7 | 0.875 | 10-9-7 | |
| 4-29-9 | 0.875 New | 4-29-9 | |
| 6-16-10 | .875 | 6-16-10 | 6-16-10 |
| 6-6-11 | .875 | 6-6-11 | 6-6-11 |
| 6-6-12 | 0.875 | 6-6-12 | 6-6-12 |
| 6-5-13 | 0.875 | 6-5-13 | 6-5-13 |
| 8-11-14 | 0.875 | 8-11-14 | 8-11-14 |
| 6-8-15 | 0.875 | 6-8-15 | 6-8-15 |
| 6-8-16 | 0.875 | 6-8-16 | 6-8-16 |
| 6-7-17 | 0.875 | 6-7-17 | 6-7-17 |
| 6-18 | 0.875 | | |
| 6-19 | 0.875 | | |

39.7749, -108.61226, 6734.7ft, 328°
04/16/2021 03:35:53 PM