



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

A.C. McLaughlin 61

Inspection 701500388

API: 05-103-12533

317°

03/23/2021 11:02:34 AM



40.10662, -108.86947, 5214.4ft, 231°
03/24/2021 11:47:31 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Top of well marker.

A.C. McLaughlin 61

Inspection 701500388

API: 05-103-12533



03/23/2021 11:02:55 AM
341°

A.C. McLaughlin 61

Inspection 701500388

API: 05-103-12533



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well marker.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well marker.

A.C. McLaughlin 61

Inspection 701500388

API: 05-103-12533



40.10658, -108.86962, 5206.8ft, 12°
03/24/2021 11:48:01 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Pit.

A.C. McLaughlin 61

Inspection 701500388

API: 05-103-12533