

Final Reclamation Inspection

April 13, 2021

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 331531

Inspection Document #: 697502785

Weld County, CO

SWSW Section 4 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WETCO FARMS #14-4
Location ID: 331531



Photo 1. Photo taken from the associated tank battery location, facing North. Photo illustrates equipment remains at the location and the establishment of winter wheat is not reflective of reference areas.

Inspection Photos
Location Name: WETCO FARMS #14-4
Location ID: 331531



Photo 2. Photo taken from the associated offsite tank battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: WETCO FARMS #14-4
Location ID: 331531



Photo 3. Photo taken from the associated offsite tank battery location, facing Southeast. See comments under Photo 1.

Inspection Photos
Location Name: WETCO FARMS #14-4
Location ID: 331531



Photo 4. Drone aerial imagery indicates that the access road and well location appear reflective of reference area vegetation.

