

Final Reclamation Inspection

April 13, 2021

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 305108

Inspection Document #: 697502787

Weld County, CO

SESW Section 4 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WETCO FARMS #24-4
Location ID: 305108



Photo 1. Photo taken from the well location, facing West. Photo illustrates the well location appears reflective of reference areas.



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: WETCO FARMS #24-4
Location ID: 305108



Photo 3. Photo taken from the well location, facing East. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: WETCO FARMS #24-4
Location ID: 305108



Photo 5. Photo taken from the associated offsite tank battery location, facing North. Photo illustrates all equipment has been removed.