

CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWNE
Location # 335393



Operator name and number not on tank.

**CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWN
Location # 335393**



Top strand of barbwire is broke.



Top strand of barbwire is broke.



CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWN
Location # 335393



Sediment and shale in culvert basin and moving thru culver.



Sediment and shale in culvert basin and moving thru culver.

CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWN
Location # 335393



Flow from culvert creating erosion on outlet side of them.



Flow from culvert creating erosion on outlet side of them.

CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWE
Location # 335393



Sediment and shale in culvert basin and moving thru culver.



Sediment and shale in culvert basin and moving thru culver.

CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWN
Location # 335393



Flow from culvert creating erosion on outlet side of them.



Flow from culvert creating erosion on outlet side of them.

CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWNE
Location # 335393



Sediment and shale in culvert basin and moving thru culver.



Sediment and shale in culvert basin and moving thru culver.

CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWN
Location # 335393



Sediment and shale in culvert basin and moving thru culver.



Sediment and shale in culvert basin and moving thru culver.

CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWNE
Location # 335393



CAERUS PICEANCE LLC
PUCKETT-66S96W 31NWNE
Location # 335393

