

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NW4

Location ID: 334073



Photo #3539 from entrance to location.



Photo #3540 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NW4

Location ID: 334073



Photo #3318 from inspection #699802835 conducted on 3/26/21.



Photo #3541 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NW4

Location ID: 334073



Photo #3319 from inspection #699802835 conducted on 3/26/21.



Photo #3542 No form of tracking control at entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NW4

Location ID: 334073



Photo #3320 from inspection #699802835 conducted on 3/26/21.