

Inspection Photos
Location Name: Wallach 1-8H
Location ID: 431888



Photo 1 – Wellhead

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Wallach 1-8H
Location ID: 431888



Photo 3 – Wellhead – Stained Soil

Photo 4 – Unused Tubing String and Rod

Inspection Photos
Location Name: Wallach 1-8H
Location ID: 431888



Photo 5 – Oily Waste in Secondary Containment

Photo 6 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Wallach 1-8H
Location ID: 431888



Photo 7 – Gas Meter



Photo 8 – Heater Treater

Inspection Photos
Location Name: Wallach 1-8H
Location ID: 431888



Photo 9 – ECD and Flare



Photo 10 – Tank Battery