

# Inspection Photos

API: 071-08670

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/19/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08670 | Date: 4/19/2021

## Inspection Photos



**Photo 1.** Facing toward the access road. Areas of erosion have been repaired and gravel was applied to the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08670 | Date: 4/19/2021

## Inspection Photos



**Photo 2.** Rip/rap outlets were installed along the road near the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08670 | Date: 4/19/2021

## Inspection Photos



**Photo 3.** Facing south toward TA well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08670 | Date: 4/19/2021

## Inspection Photos



**Photo 4.** Facing north toward the other TA well.



## Inspection Photos



**Photo 5.** Risers have been locked out.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08670 | Date: 4/19/2021