

Inspection Photos

API: 071-08273

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 4/19/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08273 | Date: 4/19/2021

Inspection Photos



Photo 1. Facing northeast toward the access road which is not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08273 | Date: 4/19/2021

Inspection Photos



Photo 2. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08273 | Date: 4/19/2021

Inspection Photos



Photo 3. Facing toward the location which was not reclaimed per 1004 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08273 | Date: 4/19/2021

Inspection Photos



Photo 4. There is now equipment being stored at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08273 | Date: 4/19/2021