

Inspection Photos

API: 071-09465

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 4/19/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09456 | Date: 4/19/2021

Inspection Photos



Photo 1. Facing southwest toward the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09456 | Date: 4/19/2021

Inspection Photos



Photo 2. Facing southwest toward the location which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09456 | Date: 4/19/2021

Inspection Photos



Photo 3. Facing north at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09456 | Date: 4/19/2021

Inspection Photos



Photo 4. Facing south at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09456 | Date: 4/19/2021

Inspection Photos



Photo 5. Facing down the east fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09456 | Date: 4/19/2021

Inspection Photos



Photo 6. Facing north at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09456 | Date: 4/19/2021