

Inspection Photos
Location Name: RUFF-66N64W /3SENW
Location #: 305536



Colorado Oil & Gas Conservation Commission
Weld
+40.517596, -104.539265
142° SE
13-Apr-2021 17:20

Photo #1

Ruff 22-3 (05-123-23107) Wellsite
Producing | PR



Colorado Oil & Gas Conservation Commission
Weld
+40.522341, -104.540915
177° S
13-Apr-2021 17:30

Photo #2

Vega 11-3, Ruff 21-3, 22-3 (West side) Battery site
Inactive | Shut-down

Inspection Photos
Location Name: RUFF-66N64W /3SENW
Location #: 305536



Photo #3

Vega 11-3, Ruff 21-3, 22-3 (East side) Battery site
Active



Photo #4

Vega 11-3, Ruff 21-3, 22-3 (West side) Battery site
Inactive | Shut-down
Battery sign

Inspection Photos
Location Name: RUFF-66N64W /3SENW
Location #: 305536



Colorado Oil & Gas Conservation Commission
Weld
+40.522291, -104.540813
84° E
13-Apr-2021 17:31

Photo #5

Vega 11-3, Ruff 21-3, 22-3 (East side) Battery site

Active

Battery sign