

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402651024

Receive Date:

04/07/2021

Report taken by:

CHRIS CANFIELD

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

### OPERATOR INFORMATION

|  |                                |                             |
|--|--------------------------------|-----------------------------|
| Name of Operator: <u>KP KAUFFMAN COMPANY INC</u> | Operator No: <u>46290</u>      | <b>Phone Numbers</b>        |
| Address: <u>1675 BROADWAY, STE 2800</u>          |                                | Phone: <u>(303) 8254822</u> |
| City: <u>DENVER</u>                              | State: <u>CO</u>               | Zip: <u>80202</u>           |
| Contact Person: <u>Jeff Rickard</u>              | Email: <u>jrickard@kpk.com</u> | Mobile: <u>( )</u>          |

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 15743Initial Form 27 Document #: 402443583

#### PURPOSE INFORMATION

- |  |  |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination                                       | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water                   |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure                             | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation                 | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project                                  |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste                      | <input type="checkbox"/> Rule 906.c.: Director request   |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input checked="" type="checkbox"/> Other <u>Quarterly Update</u>  |

#### SITE INFORMATION

N Multiple Facilities ( in accordance with Rule 909.c. )

|  |                            |                            |                               |
|--|----------------------------|----------------------------|-------------------------------|
| Facility Type: <u>SPILL OR RELEASE</u>           | Facility ID: <u>476918</u> | API #: <u></u>             | County Name: <u>WELD</u>      |
| Facility Name: <u>Robert G Berge #2</u>          |                            | Latitude: <u>40.074685</u> | Longitude: <u>-104.854142</u> |
| ** correct Lat/Long if needed: Latitude: <u></u> |                            | Longitude: <u></u>         |                               |
| QtrQtr: <u>SWSE</u>                              | Sec: <u>2</u>              | Twp: <u>1N</u>             | Range: <u>67W</u>             |
| Meridian: <u>6</u>                               |                            | Sensitive Area? <u>Yes</u> |                               |

#### SITE CONDITIONS

General soil type - USCS Classifications SPMost Sensitive Adjacent Land Use CroplandIs domestic water well within 1/4 mile? YesIs surface water within 1/4 mile? YesIs groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- ☒ E&P Waste      ☐ Other E&P Waste      ☐ Non-E&P Waste
- ☒ Produced Water      ☐ Workover Fluids
- ☒ Oil      ☐ Tank Bottoms
- ☐ Condensate      ☐ Pigging Waste
- ☐ Drilling Fluids      ☐ Rig Wash
- ☐ Drill Cuttings      ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

## DESCRIPTION OF IMPACT

| Impacted?    | Impacted Media | Extent of Impact | How Determined                           |
|--------------|----------------|------------------|--|
| UNDETERMINED | GROUNDWATER    | Unknown          | Undetermined                             |
| Yes          | SOILS          | 10'x 10' area    | Visual of initial excavation activities. |
| UNDETERMINED | SURFACE WATER  | Unknown          | Undetermined                             |

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

KPK immediately shut-in well upon notification of flowline release. A vac truck was brought in to remove any fluids that had pooled at the surface of the release location. Release occurred in close proximity to a active irrigation ditch (Brantner Ditch). Hydrocarbon fluid released from the flowline was leeching from the western ditch wall into the water. KPK installed multiple sections of booms to try and contain any hydrocarbon fluid that was being released into the water. Initial excavation work was conducted to remove impacted soil; however, due to increased water flow from the irrigation ditch, initial excavation work needed to be backfilled and the ditch wall reconstructed. Excavation will not be able to reuse until ditch ceases operations for the season.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Additional details regarding site investigation activities, including soil borings to delineate the extent of impact, have been included in the attached Site Investigation Plan. Once the ditch has ceased operations for the season (est. late October 2020), excavation activities will begin to remove impacted material from the flowline release area. Final vertical and horizontal extent of excavation area will be based results of soil boring site investigation and on results from collected grab soil samples. All soil samples will be analyzed for TPH - DRO, GRO & ORO, BTEX, pH, EC, and SAR and verified compliant with COGCC Table 910-1. At a minimum, one grab sample will be collected from each excavation wall as well as from the base of the excavation area.

### Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

A temporary groundwater monitoring well is planned to be installed to collect at least one (1) groundwater sample. Groundwater sample will be analyzed for BTEX. Additional details regarding groundwater sampling have been included in the attached Site Investigation Plan.

### Proposed Surface Water Sampling

☒ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Surface water samples will be collected per the requirements the COAs of the Spill/Release Report (Doc #402428176). Additional details regarding surface water sampling have been included in the attached Site Investigation Plan.

## Additional Investigative Actions

☒ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Additional investigative actions to delineate the extent of impact while the ditch is still in service has been attached.

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 2

Number of soil samples exceeding 910-1 1

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 25

### NA / ND

-- Highest concentration of TPH (mg/kg) 1000

NA Highest concentration of SAR

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 5

### Groundwater

Number of groundwater samples collected 1

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) 14'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 0

ND Highest concentration of Benzene (µg/l)

ND Highest concentration of Toluene (µg/l)

ND Highest concentration of Ethylbenzene (µg/l)

ND Highest concentration of Xylene (µg/l)

NA Highest concentration of Methane (mg/l)

### Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Additional details regarding site investigation have been included in the attached Site Investigation Plan.

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

All impacted soil will be excavated and hauled to a certified disposal location.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Excavation will be performed to remove all impacted soil. Impacted soil will be brought to a certified disposal facility to be disposed of. If groundwater is found to be impacted, a groundwater monitoring plan will be submitted for review and approval to address groundwater known impacts. Excavation activities to remove impacted soil will not be able to begin until the Fall when the irrigation ditch is dry.

## Soil Remediation Summary

☐ In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Other \_\_\_\_\_

☒ Ex Situ

Yes \_\_\_\_\_ Excavate and offsite disposal

If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 10

Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_

\_\_\_\_\_ Excavate and onsite remediation

\_\_\_\_\_ Land Treatment

\_\_\_\_\_ Bioremediation (or enhanced bioremediation)

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

☐ \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

☐ \_\_\_\_\_ Chemical oxidation

☐ \_\_\_\_\_ Air sparge / Soil vapor extraction

☐ \_\_\_\_\_ Natural Attenuation

☐ \_\_\_\_\_ Other \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

## REMEDATION PROGRESS UPDATE

### PERIODIC REPORTING

**Frequency:** ☒ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other \_\_\_\_\_

**Report Type:** ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☒ Other Site Investigation Report \_\_\_\_\_

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes \_\_\_\_\_

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

None

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_ 0

E&P waste (solid) description Hydrocarbon Impacted Soil \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: Denver Regional Landfill \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_ 0

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDATION COMPLETION REPORT

### REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No \_\_\_\_\_

Do all soils meet Table 910-1 standards? \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? \_\_\_\_\_

Does Groundwater meet Table 910-1 standards? \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Area of excavation will be backfilled with clean fill dirt. Backfilled excavation area will be contoured, ripped, and seeded Any portion of the irrigation ditch deconstructed during the excavation process will be rebuilt using materials approved by the ditch company.

Is the described reclamation complete? No \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? No \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? No \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 07/23/2020

Date of commencement of Site Investigation. 07/23/2020

Date of completion of Site Investigation. \_\_\_\_\_

### REMEDIAL ACTION DATES

Date of commencement of Remediation. 11/02/2020

Date of completion of Remediation. \_\_\_\_\_

### SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

### OPERATOR COMMENT

This form is being submitted as the quarterly update required by rule. Project#15743, the Robert Burge #2, is being backfilled. It will remain backfilled until the fall when the adjacent irrigation ditch is drained for the season. KPK believes it has removed the majority of the impacted soil but has not taken lab samples at this time.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jeff Rickard

Title: Regulatory

Submit Date: 04/07/2021

Email: jrickard@kpk.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: CHRIS CANFIELD

Date: 04/21/2021

Remediation Project Number: 15743

### Condition of Approval

#### COA Type

#### Description

|        |  |
|--------|--|
|        | Operator will submit a specific implementation schedule in accordance with Rule 901.d.(1).   |
|        | Per Rule 913.d.(2) Operator shall submit a Supplemental Form 27 with an updated Implementation Schedule at least 14 days in advance of any schedule changes. |
| 2 COAs |  |

### Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

#### Att Doc Num

#### Name

|           |                                |
|-----------|--------------------------------|
| 402651024 | FORM 27-SUPPLEMENTAL-SUBMITTED |
|-----------|--------------------------------|

Total Attach: 1 Files

### General Comments

#### User Group

#### Comment

#### Comment Date

|  |  |                     |
|--|--|---------------------|
|  |  | Stamp Upon Approval |
|--|--|---------------------|

Total: 0 comment(s)